




GISON Pneumatic Tools

GP-820 Air Screw Driver



PARTS LIST

✳ :Consuming Part

Item No.	Part No.	Description	Qty.	Item No.	Part No.	Description	Qty.
1	82001	Front Cap	1	21	82021	Pin (ø 2x18)	1
2	82002	Bushing	1	22	82022	Rear Plate	1
3	82003	Washer	1	23	82023	Ball Bearing (626)	1
4	82004	Ring	1	24	82024	Washer	1
5	82005	Ring	1	25	82025	O-Ring (P2x1.5)	1
6	82006	Anvil	1	26	82026	Driver	1
7	82007	Iron Ball (ø 1/8")	1	27	82027	Handle	1
8	82008	Spring	1	28	82028	Bushing	1
9	82009	Pin (ø 4x26)	2	29	82029	Pin (ø 2x6)	1
10	82010	Hammer	2	30	82030	Spring	1
11	82011	Hammer Case	1	31	82031	Reverse Valve	1
12	82012	Hammer Cam	1	32	82032	Retaining Ring	1
13	82013	Washer	1	33	82033	O-Ring (P7x1.9)	1
14	82014	Bolt	1	34	82034	Steel Ball (ø 8mm)	1
15	82015	Ball Bearing (608)	1	35	82035	Spring	1
16	82016	Front Plate	1	36	82036	Muffler	1
17	82017	Rotor	1	37	82037	O-Ring (P8x1.5)	1
18	82018	Rotor Blade	6	38	82038	Air Inlet	1
19	82019	Pin (ø 2x6)	1	39	82039	Hook	1
20	82020	Cylinder	1				